


Part No. 12458
Process Tube Adapter Kit



See inside for instructions.

ROBINAIR®

Part No. 12458 Process Tube Adapter Kit

REPLACEMENT PARTS

Seals (2 ea. required)

43539	3/16"	43537	5/16"
43538	1/4"	43536	3/8"


Washers (4 ea. required)

43543	3/16"	43541	5/16"
43542	1/4"	43540	3/8"

43546 Replacement Case

No. 12458 Process Tube Adapter Kit provides the fastest and easiest means for connecting charging lines to process tubes for evacuating and recharging a system. The design ensures an absolute seal between the tubing and the charging hose. It eliminates the need for flaring and the possibility of tubing chips getting into the system.

Design, specifications, and materials are subject to change without notice.



WARNING: To prevent personal injury when working with refrigerant,


- Operator must have a basic knowledge of repairing an A/C refrigerant system.
- Wear safety goggles when working with refrigerants.
- Point hoses away from you and anyone nearby.
- Follow the manufacturer's instructions for depressurizing the system.



Instructions

Depressurize the system following the manufacturer's instructions. Adapter parts and tubing must be free of oil and moisture.

1. Install a piercing valve on the process tube. (See illustration at right.)
2. Cut the end off the process tube behind the pinch-off point or solder.
3. Slide the cap and the appropriate size seal and washer assembly (for 3/16", 1/4", 5/16", or 3/8" tubing) onto the process tube.
4. Thread the body into the cap until it is hand tight.
5. Connect the charging line. Evacuate and recharge the system.
6. Use Robinair No. 12396 Pinch-off Tool, not included, to crimp the tubing.
7. Remove the process fitting.
8. Solder the end of the process tube.



ROBINAIR

655 Eisenhower Drive
Owatonna, MN 55060 USA
Technical Services: 1-800-822-5561
Fax: 1-866-259-1241
Customer Service: 1-800-533-6127
Fax: 1-800-322-2890
Web Site: www.robinair.com